

Результаты обработки машины Opel Astra

- Существенно снизились вибрация и шум
- Расход топлива уменьшился на 13%

| Car | Opel Astra | | | |
|-------------------------------|------------|--------|------------|------------|
| Full kilometrage | 106540 | 106632 | 106900 | 107870 |
| Kilometrage after application | | 92 | 360 | 1330 |
| Oil level | MAX | MAX | MAX-0.2 kg | MAX-0.5 kg |
| Compression | | | | |
| 1° | 9 | 14.4 | 14.9 | 14.9 |
| 2° | 6.5 | 14.4 | 14.8 | 15.3 |
| 3° | 12.5 | 14.4 | 14.8 | 15.2 |
| 4° | 14.4 | 14.4 | 14.9 | 15.3 |
| Exhaust gases | | | | |
| The gas temperature | 55 °C | 55 °C | 55 °C | 55 °C |
| CO | 1.2-1.7 % | 0.06% | 0.06% | 0.00% |
| CO ₂ | 14% | 14% | 13.70% | 14% |
| O ₂ | 0.48% | 0.25% | 1.20% | 0.51% |



